

**REPORT OF THOROUGH EXAMINATION**

As Required By The Lifting Operations and Lifting Equipment Regulations (LOLER) 1998

<b>Date of Examination &amp; Test</b> 7 <sup>th</sup> July 2018	<b>Report No.</b> 3147/18
---	---------------------------

<b>Loader / Attachment Make</b> <b>Fassi</b>	<b>Type</b> <b>F660AXP.26</b>	<b>Serial No.</b> 6202-2263 <b>Date of Manufacture</b> 2009
---	----------------------------------	--

<b>Stabiliser/s Spread. Main</b> 8.5m <b>Remote</b> 5.5m <small>Note:- Rated capacities quoted below only apply with stabiliser/s set in the above operating position</small>	<b>Specific Operating Conditions</b> <b>Firm Level Ground</b>
---	--

<b>Name and Address of Equipment Owner or Employer</b> <b>K Transport Services Ltd</b> Parkside Garage, Old Stafford Road Slade Heath, Nr. Coven,Wolverhampton, WV10 7PH	If the test was not performed at this address, state where it was carried out  <b>The Crane Centre Ltd</b>
---	--

<b>Lorry-Loader Mounting Details</b> Front	<b>Reg. No / Chassis No</b> MX57MBY
--	-------------------------------------

<b>Date of the most recent test and examination:</b>	13 <sup>th</sup> January 2018
<b>Number of the record issued on that occasion:</b>	3020/18

<b>Reason for Test</b> <small>(please tick)</small>	<b>Commissioning</b> LOLER 6 <input type="checkbox"/>	<b>Annual</b> LOLER 9.3.a(ii) or Company Specific * <input checked="" type="checkbox"/>	<b>4 Yearly</b> BS 7121-2 <input type="checkbox"/>	<b>Exceptional Circumstances</b> LOLER 9.3.a.(iv) <input type="checkbox"/>
--	--	---	---	---

<b>Rated capacities &amp; overloads applied</b> <small>Note:- Adjacent rated capacities include any hook, attachments, slings, chains, etc. i.e. the weight of the hook, attachments, slings, etc. must be included as part of the load.</small>	<b>RADIUS (m)</b>	<b>RATED LOAD (kg)</b>	<b>TEST LOAD (kg)</b>	<b>OVER-LOAD (%)</b>
	4.20	13.520		
	7.65	7.295		
	11.65	4.665		
	13.80	3.925	4318	10

**Condition:** Please give details of any specialist systems fitted to the crane, e.g. stabiliser interlocks, over the cab de-rates, manual extensions, etc.

None

**Defects noted and alterations or repairs required** None

**To be repaired immediately (before loader is put into service) or by** / /

**Latest date by which the next examination must be carried out** 6<sup>th</sup> January 2019


I hereby certify that the lorry loader described in this certificate was tested and examined on the date given, that the above particulars are correct, that it is installed correctly and that it is safe to operate.

The travelling height label and indicator is set at 13ft 6in.

**Signature** ... *Mark Jones* ..... **Qualification** .....Engineer **Date** 7<sup>th</sup> July 2018

Authenticated by:

**Name** ..... *M V McHale* .....

**Signature** 

**Address** ...The Crane centre Ltd.....

**The Crane Centre Ltd**  
**Station Road**  
**Sandbach**  
**Cheshire**  
**CW113JG**  
[www.cranecentre.co.uk](http://www.cranecentre.co.uk)