

### REPORT OF THOROUGH EXAMINATION

As Required By The Lifting Operations and Lifting Equipment Regulations (LOLER) 1998

<b>Date of Examination &amp; Test</b> 30 <sup>th</sup> July 2021		<b>Report No.</b> 5799/21		
<b>Loader / Attachment Make</b> <b>Fassi</b>		<b>Type</b> <b>V30</b>		
		<b>Serial No.</b> 8002-0438		
<b>Stabiliser/s Spread. Main</b> 8360mm <b>Remote</b> 8610mm		<b>Date of Manufacture</b> 2021		
Note:- Rated capacities quoted below only apply with stabiliser/s set in the above operating position		<b>Specific Operating Conditions</b> <b>Firm Level Ground</b>		
<b>K Transport Services</b> <b>Parkside Garage, Old Stafford Road</b> <b>Slade Heath</b> <b>Wolverhampton</b> <b>WV10 7PH</b>		If the test was not performed at this address, state where it was carried out  <b>The Crane Centre Ltd</b>		
<b>Lorry-Loader Mounting Details: Front</b>		<b>Reg. No / Chassis No</b> BV21 HBA		
<b>Date of the most recent test and examination:</b>		None		
<b>Number of the record issued on that occasion:</b>		None		
<b>Reason for Test</b> (please tick)	<b>Commissioning</b> LOLER 6 <input checked="" type="checkbox"/>	<b>Annual</b> LOLER 9.3.a(ii) or Company Specific * <input type="checkbox"/>	<b>4 Yearly</b> BS 7121-2 <input type="checkbox"/>	
			<b>Exceptional Circumstances</b> LOLER 9.3.a.(iv) <input type="checkbox"/>	
<b>Rated capacities &amp; overloads applied</b> Note:- Adjacent rated capacities include any hook, attachments, slings, chains, etc. i.e. the weight of the hook, attachments, slings, etc. must be included as part of the load.	<b>RADIUS (m)</b>	<b>RATED LOAD (kg)</b>	<b>TEST LOAD (kg)</b>	<b>OVER-LOAD (%)</b>
	6.65	9,000		
	7.55	7,730		
	11.60	4,940		
	13.70	4,145	5,181	25
<b>Condition:</b> Please give details of any specialist systems fitted to the crane, e.g. stabiliser interlocks, over the cab de-rates, manual extensions, etc.				
<b>FSC-S II Load monitoring over the cab, this is monitored over the cab and is variable depending on the load / ballast left on the truck, the more load / ballast left of the truck means more stability over the cab.</b>				
<b>Defects noted and alterations or repairs required</b>				None
<b>To be repaired immediately (before loader is put into service) or by</b> / /				
<b>Latest date by which the next examination must be carried out</b>				29 <sup>th</sup> January 2022


I hereby certify that the lorry loader described in this certificate was tested and examined on the date given, that the above particulars are correct, that it is installed correctly and that it is safe to operate.

The travelling height label and indicator is set at 13 feet 4 inches

**Signature** ... *James Bettley* ..... **Qualification** ..... *Engineer*      **Date:-** 30<sup>th</sup> July 2021

Authenticated by:

**Name** ... *M V McHale*.....

**Signature** 

**Address** ... The Crane centre Ltd.....

**The Crane Centre Ltd**  
Station Road  
Sandbach  
Cheshire  
CW113JG  
[www.cranecentre.co.uk](http://www.cranecentre.co.uk)